




Environmental Solutions through Technology

TRC Environmental Corporation
Boott Mills South, Foot of John Street
Lowell, MA 01852
☎ (508) 970-5600

April 27, 1993

Mr. Harish Panchal
Bureau of Waste Site Cleanup
Department of Environmental Protection
One Winter Street, Fifth Floor
Boston, MA 02108



Superfund
SITE: 80/90 Bridge Street
BREAK: 1.2
OTHER: 596490

Subject: Final Preliminary Assessment Report
80/90 Bridge Street Property
Newton, Massachusetts
W.A. No. 09-1JZZ
Reference No. 1-636-010-0-1J17, TDD No. 9202-19-ATP
CERCLIS No. MAD001071034

Dear Mr. Panchal:

A copy of the Final Site Inspection Report for the 80/90 Bridge Street property in Newton, Massachusetts is enclosed. The Final Report has been revised in accordance with comments received from the EPA and the State. The appendix submitted with the Draft Report did not require revision. Therefore, appendix documentation is not included with the Final Report.

If you have any questions, please do not hesitate to call.

Sincerely,

Paul A. Hughes
ARCS Program Manager

Enclosure

cc: S. Hayes, EPA WAM (w/o enclosure)
N. Smith, EPA SAM (w/o enclosure)
I. Babroudi, MADEP CRO